

M 16

# Montageanleitung

Assembly Instruction


**IMS** CONNECTOR SYSTEMS

HF-Steckverbinder  
RF Connectors

Steckergehäuse  
Connector housing

Hülse  
Ferrule

Innenleiter  
Centre conductor



löten  
solder

crimpen  
crimp

